

FIG. 1

FIG. 100 = 1000000




FIG. 2A

$P_{100} (300(x), 600(y), 100(z))$   
 $P_0 (300(x), 600(y), 0(z))$




FIG. 2B




FIG. 2C

FIG. 3A




FIG. 3B




FIG. 3C





FIG. 3D



PRESSURE-SENSING VALUE	VELOCITY COEFFICIENT
0 ~ 5	1
6	E 1
7	E 2
⋮	⋮
2 5 5	E 2 5 5

FIG. 4A

PRESSURE-SENSING VALUE	VELOCITY COEFFICIENT
0 ~ 5	1
6	F 1
7	F 2
⋮	⋮
2 5 5	F 2 5 5

FIG. 4B




FIG. 5




FIG. 6




FIG. 7




FIG. 8






FIG. 9




FIG. 10A




FIG. 10B




FIG. 10C




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16






FIG. 17




FIG. 18